

Addendum to Agenda Item 6 of the Meeting of the River Hamble Harbour  
Management Committee on Friday 20 December 2024

- 6.52 25 Nov. Assistance given in pumping out a resident motor vessel. Located a buoy reported as off station by an adjacent Harbour Authority. Yard clearance. Refurled loose genoa on a midstream moored yacht and liaison with owner.
- 6.53 26 Nov. Responded to a call from a member of the public reporting a person stuck in the mud in the Upper River. Liaison with HM Coastguard. Person made own way to safety. Inspection of RHCP jetty, damaged by barbecue. Assistance given to HM Coastguard and Southampton HM in recovery of an electric RIB with a battery fire. Extinguished and recovered.
- 6.54 27 Nov. Jet wash clean of Fishermens' Jetty Warsash. Yard clearance work. Patrol craft anode replacement.
- 6.55 28 Nov. CCTV maintenance work Warsash. Warsash Bridge bannister painting.
- 6.56 29 Nov. Patrol to Curbridge. Branch removal. Continuation of bannister painting at Warsash. Disentanglement of two moored vessels, one of whose moorings had dragged. Liaison with mooring owner to rectify. Light inspection.
- 6.57 30 Nov. Liaison with mooring contractor at 6.56. Advice given after sunset to owner of unlit small craft. Light inspection.
- 6.58 01 Dec. Light traffic.
- 6.59 02 Dec. Attended Swanwick following complaint that the slipway there was blocked by a skip. Slipway accessible with skip being temporarily in position to remove waste. Commercial fitting of replacement pile lines. Yard clearance.
- 6.60 03 Dec. Assistance given to Hampshire Marine Police Unit.
- 6.61 04 Dec. Check of a resident motor vessel on behalf of her owner. Fitting of Christmas display.
- 6.62 05 Dec. Pump out of an inundated small fishing vessel at Warsash.
- 6.63 06 Dec. Jet wash of Warsash Jetty and Bridge facilities. Check of vessels on midstream Visitors' Pontoon prior to forecast poor weather.
- 6.64 07 Dec. Strong winds. Storm Darragh. Direction North of West therefore effect reduced. Re-furled sails on three midstream moored vessels. Liaison with the Crown Estate mooring contractor regarding a loose pile iron. Temporary securing arrangements put in place. Recovered a kayak from the Eastern Shore to Warsash.

- 6.65 08 Dec. Resecured a loose mainsail on a midstream moored yacht. Lashed down a torn headsail on a mid-stream moored yacht. Liaison with owners. Towed a small, broken down motor vessel to a boatyard for defect rectification.
- 6.66 09 Dec. Assistance given to mooring contractors to resolve pile iron partial failure. Liaison with a private mooring contractor regarding a mooring which had appeared to have dragged. Routine liaison with Hampshire Marine Police Unit. Further support to the Crown Estate mooring contractor.
- 6.67 10 Dec. Commercial tow of a yacht from a temporary berth to her proper mooring. Further light inspection to check a particular failure.
- 6.68 11 Dec. Tide gauge cleaning.
- 6.69 12 Dec. Movement of vessels associated with partial pile iron failure to temporary moorings.
- 6.70 13 Dec. Maintenance of black water pump-out facility at Warsash. Repositioned fenders on several midstream moored vessels. Pump out of inundated tenders at Warsash.
- 6.71 14 Dec. Light traffic.
- 6.72 15 Dec. Commencement of return of vessels displaced at 6.64. Liaison with owners.
- 6.73 16 Dec. Return of 4 vessels to their proper moorings following pile maintenance works. Replaced parted stern line with temporary mooring lines on a mid-stream moored yacht. Liaison with owner.