

## Addendum to Agenda Item 6 of the Meeting of the River Hamble Harbour Board on Friday 10 January 2020

- 5.29. 12 Dec. Patrol conducted mooring and pontoon checks. Building vacated for ceiling replacement work.
- 5.30. 13 Dec. Patrol conducted mooring and pontoon checks. Channel clearance work near the Horse and Jockey. Tree survey in the Upper River.
- 5.31. 14 Dec. Patrol conducted mooring and pontoon checks. Bird survey support.
- 5.32. 15 Dec. Patrol conducted mooring and pontoon checks. Litter pick at River Hamble Country Park Jetty.
- 5.33. 16 Dec. Patrol conducted mooring and pontoon checks. Tow of a mid-stream moored yacht from her proper mooring prior to planned maintenance work. Patrol craft anti-fouling inspection. Office refurbishment work.
- 5.34. 17 Dec. Patrol conducted mooring and pontoon checks. Office refurbishment work. Yard clearance.
- 5.35. 18 Dec. Patrol conducted mooring and pontoon checks. Operational and Safety Meeting. Patrol gave assistance to a mid-stream moored yacht in departing her berth in strong winds.
- 5.36. 19 Dec. Patrol conducted mooring and pontoon checks. Jetty light replacement. Planned patrol boat maintenance. Office refurbishment work.
- 5.37. 20 Dec. Patrol conducted mooring and pontoon checks. Office refurbishment work. Liaison with the Crown Estate Mooring Contractor regarding forthcoming pile maintenance programme.
- 5.38. 21 Dec. Patrol conducted mooring and pontoon checks. Litter pick at River Hamble Country Park Jetty.
- 5.39. 22 Dec. Patrol conducted mooring and pontoon checks. Support to seasonal dinghy racing. Office refurbishment work.
- 5.40. 23 Dec. Patrol conducted mooring and pontoon checks. Office refurbishment work. Patrol boat maintenance work.
- 5.41. 24 Dec. Patrol conducted mooring and pontoon checks. Responded to a call from a member of the public reporting a tender in difficulties off Hamble. Tender had experienced engine cut-out in strong ebb and higher winds. Oars not carried. On attendance, tender located with occupant on a mid-stream moored yacht (not his). Returned to adjacent Sailing Club and guidance given on carrying an alternative means of propulsion. Occupant uninjured. Liaison with the Crown Estate Mooring Contractor regarding pile maintenance. Liaison with Hampshire Marine Police Unit. Responded to a call from a member of the public reporting an outfall marker post failure off Hamble.

- 5.42. 25 Dec. Office closed.
- 5.43. 26 Dec. Patrol conducted mooring and pontoon checks. High winds. Liaison with sailing clubs regarding forecast weather for seasonal sailing programme. Light traffic. Patrol recovered a large part of a tree from the Main Channel in the Upper River – towed to the bank for subsequent cutting and removal.
- 5.44. 27 Dec. Patrol conducted mooring and pontoon checks. Re-secured Christmas afloat decorations following high winds.
- 5.45. 28 Dec. Patrol conducted mooring and pontoon checks. Liaison with a moored yacht owner on the 'V' run reporting collision damage believed sustained while alongside his mooring. Assistance given in contacting the other party. Liaison with a school yacht regarding overstay on the mid-stream Visitors' Pontoon.
- 5.46. 29 Dec. Patrol conducted mooring and pontoon checks. Support to Foxer dinghy racing. At 1500 in failing light responded to a call from a member of the public reporting a vessel sunk outside the Main Channel at her boatyard mooring between the M27 and Rail bridges. Vessel not a danger to traffic. Records commenced and PolRep issued. Area boomed effectively and observed. Owner contacted through yard. Initial investigations revealed that tanks were empty (engines non-operational) and relatively low egress bilge related. Recovery planning commenced. Regulator updated.
- 5.47. 30 Dec. Patrol conducted mooring and pontoon checks. Booming inspection (reinforcement) of wreck at 5.46. Light and irregular egress of diesel from wreck, contained within booming. Records taken. Liaison with boatyard and follow-up reports made to the Regulator.
- 5.48. 31 Dec. Patrol conducted mooring and pontoon checks. Further recovery planning with insurers' involvement. Verbal and written updates given to the Regulator. Patrol stopped a speeding motor boat off Warsash and administered a verbal warning.
- 5.49. 01 Jan. Patrol conducted mooring and pontoon checks. Support to New Year's Day raft racing off Warsash. Refinement of wreck disposal planning.
- 5.50. 02 Jan. Patrol conducted mooring and pontoon checks. Diving work to inspect the wreck and fit lifting bags commenced. Preparation for planned lift  
03 Jan. Patrol attended a vessel reported to be low in the water. On arrival, a small amount seen to be present in bilge. Monitored and owner contacted.
- 5.51. 03 Jan. Patrol conducted mooring and pontoon checks. Sunk vessel re-floated and moved to scrubbing piles for hull inspection and sealing to make watertight. Contaminated material recovered and disposed of by the yard.
- 5.52. 04 Jan. Patrol conducted mooring and pontoon checks. Aid to Navigation check. Office refurbishment work.
- 5.05. 05 Jan. Patrol conducted mooring and pontoon checks.