Addendum to Agenda Item 6 of the Meeting of the River Hamble Harbour Board on Friday 12 April 2024

- 7.45 27 Feb. Pump out of inundated craft at Warsash. Targeted moorings check on behalf of Moorings Officer.
- 7.46 28 Feb. Marina liaison. Routine patrol craft maintenance. Light traffic.
- 7.47 29 Feb. Recovered a large log rom the Main Channel in the Upper River.
- 7.48 01 Mar. Check of a mid-stream moored yacht on behalf of her owner. Pumped out cockpit. Liaison with owner. Commercial tow of a yacht. Resecured a loose halyard and block on a mid-stream moored yacht. Recovered No 11 light from the Shore adjacent to the Pink Ferry hut. Light showed signs of collision. CCTV investigation proved that light had been working throughout the night until around 0400 in foul weather when an inbound vessel (unidentifiable) had struck the mark off Warsash College Jetty. Light base repaired and light refitted.
- 7.49 02 Mar. Preparations for Trinity House Light Audit (4 March). Pumped out inundated yacht at owner's request.
- 7.50 03 Mar. Recovered a large branch from the Main Channel off Bursledon.
- 7.51 04 Mar. Pump-out of inundated tenders at Warsash. Survey of RHCP Jetty. Liaison with Hampshire Marine Police Unit regarding persons of interest. Annual Trinity House Light Inspection.
- 7.52 05 Mar. Liaison with Hampshire Marine Police Unit. Light traffic in heavy rain.
- 7.53 06 Mar. Attended RHCP Jetty following a report of a missing deck board. Replaced.
- 7.54 07 Mar. Liaison visit from HCC Wildlife Crime Police Officer. Liaison with Hampshire Marine Police Unit regarding persons of interest. Commercial fitting of new pile lines.
- 7.55 08 Mar. Liaison with a mooring holder and the Crown Estate Mooring contractor regarding pontoon chain failure.
- 7.56 09 Mar. Recovery of failed swinging mooring buoy to Warsash. Boat coding work.
- 7.57 10 Mar. Cleaning of small craft safety signage at Swanwick. Berthing assistance given to a motor vessel in difficulty. Replacement of tidal gauge at Crableck. Routine liaison with Hamble Lifeboat.
- 7.58 11 Mar. Recovered a large branch from the Main Channel in the Upper River. Pumped out inundated tenders at Hamble Jetty. Pile Survey at exceptional Low Water (0.3m above Chart Datum).

- 7.59 12 Mar. Continuation of LW pile survey (0.3m above CD). Tide auge maintenance
- 7.60 13 Mar. Mooring inspection on behalf of mooring holder. Commercial making up of mooring lines.
- 7.61 14 Mar. First Aid equipment checks. Maintenance of Aids to Navigation.
- 7.62 15 Mar. Commercial fitting of new pile lines. Stood by a motor vessel aground on Hook Spit (rising tide, lee shore). Successfully refloated.
- 7.63 16 Mar. Assisted a mid-stream mooring holder in replacement of pile lines. Attended Hamble Quay following a report of diesel on the surface. No source apparent. Broken up with jet wash. Assistance given to new mooring holder in picking up his mooring.
- 7.64 17 Mar. Placing of reservation boards on Hamble Jetty. Yard clearance work at Warsash.
- 7.65 18 Mar. Commercial towing in preparation for the Crown Estate's routine pile replacement programme. Liaison with affected owners. Tide gauge cleaning.
- 7.66 19 Mar. Further liaison with mooring holders affected by the Crown Estate pile replacement programme. Preparations for the visit of a tall ship.
- 7.67 20 Mar. Support to visit of tall ship and Sea Cadets. Black water pump-out defect rectification.
- 7.68 21 Mar. Interviews for seasonal patrol officer roles. Support to Eastleigh and Fareham Borough Councils' ecology planning officers (Boat trip and briefing HM/Environment Officer).
- 7.69 22 Mar. Interviews for seasonal patrol officer roles. Preparations for Crown Estate pile replacement programme.
- 7.70 23 Mar. Preparations for Crown Estate pile replacement programme. Seasonal patrol officer interview review. Patrol craft maintenance.
- 7.71 24 Mar. Towed three vessels from their moorings to mid-stream Visitors' Pontoon in preparation for Crown Estate pile replacement programme. Boat coding work.
- 7.72 25 Mar. Tow of three vessels from their moorings to the mid-stream Visitors' Pontoon in preparation for the Crown Estate pile replacement programme. Preparation for Sea Cadet vessel visit.
- 7.73 26 Mar. Routine advisory meeting with local start-up paddleboard company. Tow of five vessels from their moorings to the mid-stream Visitors' Pontoon in preparation for the Crown Estate pile replacement programme.
- 7.74 27 Mar. Light traffic.
- 7.75 28 Mar. Fender re-positioning and line checking in high winds (Storm NELSON). Refurled flogging jib on mid-stream moored yacht.

- 7.76 29 Mar. Enhanced mooring checks in strong winds. Assistance given to a yacht in securing at Hamble Jetty. Liaison with Crown Estate mooring contractor regarding pontoon float failure. Recovery of detached pontoon float. Re-secured flogging headsails on four mid-stream moored yachts. Re-secured loose halyard on a mid-stream moored yacht off Bursledon. Towing assistance given to a small yacht with outboard engine failure. Responded to a report of a pontoon chain failure, causing the pontoon to become detached and impact another vessel. Pontoon secured. Further liaison with the Crown Estate mooring contractor.
- 7.77 30 Mar. Enhanced mooring checks following strong winds. Re-positioning of fenders and adjustment of lines. Liaison with owners affected. Towed a launch with propulsion failure to her Club. Liaison with the Crown Estate mooring contractor.
- 7.78 31 Mar. Continuation of enhanced mooring checks following strong winds. Liaison with owners affected.
- 7.79 O1 Apr. Continuation of enhanced mooring checks following strong winds. Liaison with owners affected.
- 7.80 02 Apr. Preparation for tall ship visit. Liaison with owner of a yacht damaged by failed pontoon. Tow of a vessel to the mid-stream Visitors' Pontoon. Routine liaison with Hampshire Police at Hamble Jetty. Re-secured loose foresail on a midstream moored yacht.
- 7.81 03 Apr. Responded to a report of pile chain failure at a mooring off Crableck.

 Pontoon temporarily secured. Liaison with owner and the Crown Estate mooring contractor. Boat coding work.
- 7.82 04 Apr. Liaison with HM Coastguard and Calshot Lifeboat, responding to a safety call from a yacht. Yacht had recovered three paddleboarders in difficulties off Calshot. Recovered to Warsash, met by Hampshire Ambulance. One casualty (child) suffering from shock, water ingestion and early onset hypothermia.
- 7.83 05 Apr. Enhanced mooring checks. Strong winds. Replacement of fenders and resecuring of lines.
- 7.84 06 Apr. Light traffic. Enhanced mooring checks. Strong winds. Replacement of fenders and re-securing of lines.
- 7.85 07 Apr. Light traffic. Further preparation for the Crown Estate pile replacement programme.
- 7.86 08 Apr. Assistance given to a small dinghy in difficulty. Liaison with the Crown Estate mooring contractor. Preparations for TS Jack Petchey (Sea Cadets). Enhanced mooring checks in advance of predicted strong winds and high tides. Total power failure at 2014. Liaison with HM Coastguard to report.
- 7.87 09 Apr. Electrical power failure defect rectification. Yard and path clearance to remove overnight debris. Liaison with excellent Fareham Borough Council team to clear foreshore. Liaison with HM Coastquard report from member of the public

reporting vessels adrift at Swanwick spurious. Assistance given to TS Jack Petchey on departure from Warsash.