

Addendum to Agenda Item 7 of the Meeting of the River Hamble Harbour Board on Friday 5 April 2019

- 4.65. 12 Mar. Patrol conducted mooring and pontoon checks. Patrol gave assistance to a tender aground on the mud off Warsash in strong SW winds. Tender and occupants recovered. Routine patrol boat maintenance.
- 4.66. 13 Mar. Patrol conducted mooring and pontoon checks. Liaison with a Sailing Club. Interview for potential seasonal coxswain.
- 4.67. 14 Mar. Patrol conducted mooring and pontoon checks. Interview for potential seasonal coxswain. Routine patrol boat maintenance.
- 4.68. 15 Mar. Patrol conducted mooring and pontoon checks. Interview for potential seasonal coxswain. Routine patrol boat maintenance.
- 4.69. 16 Mar. Patrol conducted mooring and pontoon checks. Strong winds. Routine patrol boat maintenance.
- 4.70. 17 Mar. Patrol conducted mooring and pontoon checks. Attended a yacht on the 'V' run. Life raft had blown over the side in strong winds (not activated). Raft recovered to pontoon. Liaison with Marina (whose mooring it was) to identify and inform owner. Routine RIB maintenance.
- 4.71. 18 Mar. Patrol conducted mooring and pontoon checks. Returned a catamaran from Warsash HM Jetty to her proper mooring at the request of her owner. Checked a commercially owned vessel, listing. On investigation, found an amount of water within the bilge. Owner contacted and vessel removed for defect rectification. Boat coding work. Checked a mid-stream moored yacht at the request of her owner.
- 4.72. 19 Mar. Patrol conducted mooring and pontoon checks. Commercial tow of a vessel to a boatyard. HM and EDM River support to Highways England and contractor's survey of the M27 Bridge drainage arrangements. Interview for potential seasonal coxswain.
- 4.73. 20 Mar. Patrol conducted mooring and pontoon checks. Routine patrol boat maintenance. Tide gauge refurbishment work.
- 4.74. 21 Mar. Patrol conducted mooring and pontoon checks. Routine maintenance of Aids to Navigation. Replacement of a section of pontoon decking. Tide gauge maintenance work. Routine patrol boat maintenance.
- 4.75. 22 Mar. Patrol conducted mooring and pontoon checks. Patrol investigated a report of a minor collision after sunset between a vessel underway and a moored yacht on the 'G' run. No damage reported. Attempts made to contact the owner.
- 4.76. 23 Mar. Patrol conducted mooring and pontoon checks. Reporting of pontoon with defective end board to her owner for defect rectification. Routine patrol boat maintenance.

- 4.77. 24 Mar. Patrol conducted mooring and pontoon checks. Freed a trapped mooring line on a mid-stream moored yacht.
- 4.78. 25 Mar. Patrol conducted mooring and pontoon checks. Patrol gave assistance to the skipper of a mid-stream moored yacht with propulsion failure off Crableck Bend. Towed to Warsash HM Pontoon at owner's request for defect rectification.
- 4.79. 26 Mar. Patrol conducted mooring and pontoon checks. Jet wash of Tide Gauges. Positioning of water safety signage at RHCP. Attended a pontoon with two persons acting apparently abnormally. On investigation, both were there with the permission of the owner. Towed a vessel with propulsion failure to the HM Jetty at Warsash for defect rectification.
- 4.80. 27 Mar. Patrol conducted mooring and pontoon checks. Boat coding work. Gave advice to a visiting yacht, practising alongside manoeuvres on the mid-stream Visitors' Pontoon.
- 4.81. 28 Mar. Patrol conducted mooring and pontoon checks. Tide Gauge replacement work. Liaison with a sailing club regarding unauthorised occupation of one of its moorings. Patrol towed the offending vessel to the mid-stream Visitors' Pontoon pending further enquiry.
- 4.82. 29 Mar. Patrol conducted mooring and pontoon checks. On conducting routine preparation for patrol, officers noticed that the duty patrol craft had had her lines removed by persons overnight in an attempt to set her adrift. The padlock arrangement had ensured that she remained secured to the Warsash HM Jetty. In addition, a dry-powder fire extinguisher had been let off on the pontoon. Examination of CCTV footage revealed that 3 males had been responsible between 2130 and 2230 on the previous evening. CCTV footage showed the three climbing into a vehicle in the Shore Road Car Park. Number Plates taken and reported to the Police. Patrol Boat made ready for operations. Patrol re-secured slack mooring lines on a mid-stream moored yacht. Patrol stopped and gave a verbal warning to a small motor boat creating excessive wash. Routine liaison with the Crown Estate mooring contractor.
- 4.83. 30 Mar. Patrol conducted mooring and pontoon checks. Advice given to sailing school visitors.
- 4.84. 31 Mar. Patrol conducted mooring and pontoon checks. On request, escorted a sailing vessel towing her consort to her proper marina berth. Patrol attended a yacht with propulsion difficulties in the mouth of the River and towed her to her proper berth in a Marina. Patrol gave assistance to a mid-stream moored yacht fouled on her mooring lines.
- 4.85. 01 Apr. Patrol conducted mooring and pontoon checks. Preparation for lift-out and planned maintenance of a patrol boat. Liaison with Paddle Boarders.
- 4.86. 02 Apr. Patrol conducted mooring and pontoon checks. Boat coding work. Routine liaison with the Crown Estate mooring contractor.