

Addendum to Agenda Item 6 of the Meeting of the River Hamble Harbour  
Management Committee on Friday 13 March 2020

- 5.36. 10 Feb. Patrol conducted mooring and pontoon checks. Continued strong winds. Enhanced mooring check following Storm Ciara. Replacement of a number of fenders and worn mooring lines and re-furling of sails and making good covers. Pump out of small motor vessel on the fishermen's moorings. Liaison with owners.
- 5.37. 11 Feb. Patrol conducted mooring and pontoon checks. Continued strong winds. Pump out of inundated tenders at Warsash. Further replacement/re-positioning of fenders and loose covers.
- 5.38. 12 Feb. Patrol conducted mooring and pontoon checks. Litter pick at River Hamble Country Park. Fitted new generator adaptors in Patrol Craft.
- 5.39. 13 Feb. Patrol conducted mooring and pontoon checks. Dismantling of abandoned/wrecked motorboat prior to disposal. Preparations for Storm Dennis. Increasing winds. Light River traffic.
- 5.40. 14 Feb. Patrol conducted mooring and pontoon checks. Building winds. Southern Water drain inspection. Preparation for Storm Dennis.
- 5.41. 15 Feb. Patrol conducted mooring and pontoon checks. Storm Dennis. Sustained very high winds and rain. Checks on moored craft at Warsash Jetty.
- 5.42. 16 Feb. Patrol conducted mooring and pontoon checks. Enhanced checks. Attended two yachts at Warsash which had sustained damage in Storm Dennis. Replaced a number of parted lines on moored vessels. Liaison with affected owners. Repair of a number of damaged cleats. Attended a number of mid-stream moored yachts to replace parted mooring lines and check vessels at owners' requests. Liaison with a marina about a resident mid-stream moored yacht with a shredded foresail.
- 5.43. 17 Feb. Patrol conducted mooring and pontoon checks. Routine marina and boatyard liaison following Storm Dennis. Further enhanced checks of mid-stream moored yachts.
- 5.44. 18 Feb. Patrol conducted mooring and pontoon checks. Routine marina and boatyard liaison following Storm Dennis. Further enhanced checks of mid-stream moored yachts. Liaison with owners affected by the forthcoming Crown Estate planned pile maintenance programme.
- 5.45. 19 Feb. Patrol conducted mooring and pontoon checks. Liaison with owners affected by the forthcoming Crown Estate planned pile maintenance programme.
- 5.46. 20 Feb. Patrol conducted mooring and pontoon checks. Re-secured a loose sail on a mid-stream moored yacht and secured a loose sail cover. Replaced

fenders on a mid-stream moored yacht. Checked vessels displaced by the Crown Estate pile maintenance programme.

- 5.47. 21 Feb. Patrol conducted mooring and pontoon checks. Assistance to Hampshire Marine Police Unit training exercise. Routine marina and boatyard liaison.
- 5.48. 22 Feb. Patrol conducted mooring and pontoon checks. Assisted a vessel displaced by the Crown Estate pile maintenance programme onto the mid-stream Visitors' Pontoon.
- 5.49. 23 Feb. Patrol conducted mooring and pontoon checks. Towed a moored yacht with battery failure to HM Pontoon for charging. Vacant berth check.
- 5.50. 24 Feb. Patrol conducted mooring and pontoon checks. Moved two yachts moored on the mid-stream Visitors' Pontoon to Hamble Point to create manoeuvring space for departing spoil barges. Liaison with affected owners. Replacement of a number of fenders on mid-stream moored yachts. Patrol responded to a call from a member of the public regarding a possibly partially decomposed animal on the footpath near the Chinese Bridge. On arrival, patrol discovered what appeared to be a white hide. Liaison with Fareham Borough Council who removed the item and re-opened the path.
- 5.51. 25 Feb. Patrol conducted mooring and pontoon checks. Liaison with a mid-stream mooring holder regarding missing pick-up lines. Fitted new pile lines to a mid-stream moored yacht at the owner's request. Routine patrol boat anti-foul testing.
- 5.52. 26 Feb. Patrol conducted mooring and pontoon checks. Re-secured loose head rope on a yacht moored at the HM Jetty Warsash. Routine Patrol Boat maintenance. Liaison with owners affected by the Crown Estate pile maintenance programme.
- 5.53. 27 Feb. Patrol conducted mooring and pontoon checks. Warned a motor vessel for not maintaining a listening watch on VHF Channel 68 during a movement of a spoil barge. Liaison with the owner of a mid-stream moored yacht reporting damage to his vessel.
- 5.54. 28 Feb. Patrol conducted mooring and pontoon checks. Replacement of pile lines on two mid-stream moored yachts.
- 5.55. 29 Feb. Patrol conducted mooring and pontoon checks. Strong winds. Routine liaison with the Crown Estate mooring contractor regarding the pile maintenance programme. Responded to a call from a member of the public reporting a fault with a yacht club pontoon. On arrival, pontoon safe but a failed cross member was witnessed. Liaison with the yacht club to secure and programme necessary repair.
- 5.56. 01 Mar. Patrol conducted mooring and pontoon checks. Inspection of temporary repairs to pontoon at 5.55. Returned two yachts to their proper

moorings as a result of progress on the pile maintenance programme. Liaison with owners. Patrol Craft anti-foul inspection

- 5.57. 02 Mar. Patrol conducted mooring and pontoon checks. Removed two yachts from their moorings in preparation for pile maintenance. Towed a further yacht to her proper mooring at the owner's request.
- 5.58. 03 Mar. Patrol conducted mooring and pontoon checks. Re-positioning of displaced yachts on the mid-stream Visitors' Pontoon to create additional space. Liaison with affected owners. Dredging operations at Swanwick complete. Moved a yacht to Stone Pier Yard for lift out.
- 5.59. 04 Mar. Patrol conducted mooring and pontoon checks. Liaison with the piling barge operating in support of the Crown Estate pile maintenance programme. Tide gauge cleaning.
- 5.60. 05 Mar. Patrol conducted mooring and pontoon checks. Liaison with a mooring holder regarding reported damage to her yacht. Photographs taken and sent to the owner.
- 5.61. 06 Mar. Patrol conducted mooring and pontoon checks. Responded to a call from a paddle boarder reporting a loose part of a pontoon float - recovered. Liaison with the Crown Estate Mooring Contractor and pile barge regarding progress of the maintenance programme. Liaison with owners. Liaison with a mooring holder regarding damage to a windvane generator.
- 5.62. 07 Mar. Patrol conducted mooring and pontoon checks. Re-positioning of displaced yachts on the mid-stream Visitors' Pontoon to create additional space. Liaison with affected owners. Stopped three Personal Water Craft (jet-skis) for the creation of excessive wash. Liaison with Hamble Life Boat in bringing a yacht with propulsion failure alongside HM jetty for defect rectification.
- 5.63. 08 Mar. Patrol conducted mooring and pontoon checks. Liaison with Hampshire fire and rescue services. Further liaison with Hamble Life Boat. Liaison with the Crown Estate Mooring Contractor and pile barge regarding progress of the maintenance programme. Liaison with owners.