

Contributory Factors Report Summary - Ancell Farm to Valmead Sch

Accidents Found Date Range: 07/06/2013 - 26/03/2018
Grid Coordinate Range: 481250,153550 - 482314,155576
Accident Date BETWEEN '01-Apr-2013' AND '31-Mar-2018'

Accident Severity
2013 2014 2015 2016 2017 2018 Total

Serious **0 3 2 1 0 0 6**

Slight **7 3 5 2 3 1 2 1**

Total **7 6 7 3 3 1 2 7**

2013 2014 2015 2016 2017 2018 Total

Serious **0 3 2 1 0 0 6**

Slight **7 9 6 4 3 3 3 2**

Total **7 12 8 5 3 3 3 8**

2013 2014 2015 2016 2017 2018 Total

Adult KSI **0 3 2 1 0 0 6**

Slight **7 9 6 4 3 3 3 2**

Total **7 12 8 5 3 3 3 8**

Casualty Severity

Casualty KSI

Ancell Farm to Valmead Sch

Accident Date BETWEEN '01-Apr-2013' AND '31-Mar-2018'

Contributory Factors Report 21-June-2018 1

Ancell Farm to Valmead Sch

Accident Date BETWEEN '01-Apr-2013' AND '31-Mar-2018'

Yes

Contributory Factors Confidence

Daylight Daylight

Surface Dry

Grid Coords 482314/153673

Accident Reference:130206416 Slight VELMEAD RD BEND NR PONDTAIL BRIDGE FLEET

Did a police

officer attend?

Possible

Possible

Possible

Very likely

Impaired by drugs (Driver/Rider - Impairment)

Impaired by alcohol (Driver/Rider - Impairment)

Loss of control (Driver/Rider - Error)

Careless/Reckless (Driver/Rider - Behaviour)

Accident 1 of 27

Participant

Vehicle 001

Vehicle 001

Vehicle 001

Vehicle 001

Friday 07/06/2013 09:20

Weather Fine without high winds

602

410

501

502

Accident Description

Vehicles

CAR TRAV NORTHWEST FROM NORRIS HILL NEG LH BEND DRIVER LOST CONTROL CAUSING VEH TO LEAVE C/WAY ON O/S AND COLLIDE WITH WALL PED ON FOOTWAY O/S NO 141 THEN STRUCK BY BRICKS

1 Car Going ahead left hand bend Skid Not contacted SE to W Male Age 20

Casualties

1 Pedestrian Slight Vehicle no.1 Female 55

Yes

Contributory Factors Confidence

Daylight Daylight

Surface Dry

Grid Coords 481545/155468

Accident Reference:130260159 Slight A3013 MINLEY RD JW NUMBER 34 FLEET

Did a police

officer attend?

Possible

Possible

Possible

Possible

Driver using mobile phone (Driver/Rider - Impairment)
Following too close (Driver/Rider - Injudicious)
Following too close (Driver/Rider - Injudicious)
Exceeding speed limit (Driver/Rider - Injudicious)
Accident 2 of 27

Participant

Vehicle 003
Vehicle 003
Vehicle 002
Vehicle 002
Sunday 14/07/2013 19:55
Weather Fine without high winds
306
308
308
508

Accident Description

Vehicles

CAR3 TRAV NORTH A3013 MINLEY RD FAILED TO STOP AND COLLIDES WITH REAR OF CAR2 IN FRONT PUSHING IT INTO REAR OF CAR1 WAITING TO TURN RIGHT INTO NUMBER 34.
1 Car Waiting to turn right No skid Negative S to N Female Age 42
2 Car Stopping No skid Negative S to N Female Age 45
3 Car Going ahead other No skid Negative S to N Female Age 63

Casualties

1 Passenger Slight Vehicle no.2 Male 16
Contributory Factors Report 21-June-2018 2
Ansell Farm to Valmead Sch
Accident Date BETWEEN '01-Apr-2013' AND '31-Mar-2018'
No - reported
'over the
counter'

Contributory Factors Confidence

Daylight Daylight
Surface Dry
Grid Coords 481565/155566
Accident Reference:130275005 Slight A3013/B3013 MINLEY RD RBT JW A3013 W/BOUND APPROACH FLEET

Did a police officer attend?

Failed to look properly (Driver/Rider - Error) Very likely
Accident 3 of 27

Participant

Vehicle 001
Tuesday 23/07/2013 20:15
Weather Unknown
405

Accident Description

Vehicles

VAN1 TRAV WEST A3013 COVE RD FAILED TO GIVE WAY AND ENTERED RBT COLLIDING WITH P/C2 TRAV SOUTH FROM B3013 MINLEY RD ALREADY ON RBT.
1 Van/Goods < 3.5t Going ahead other No skid Not contacted E to W Male Age -1
2 Pedal Cycle Going ahead other No skid Not applicable N to S Male Age 50

Casualties

1 Driver or Rider Slight Vehicle no.2 Male 50
Yes

Contributory Factors Confidence

Daylight Daylight
Surface Dry
Grid Coords 482076/155453
Accident Reference:130311665 Slight A3013 ANCELLS RD RBT A3013 COVE RD EXIT FLEET

Did a police officer attend?

Possible
Very likely
Very likely
Very likely
Inexperienced or learner driver/rider (Driver/Rider - Behaviour)
Loss of control (Driver/Rider - Error)
Poor turn or manoeuvre (Driver/Rider - Error)
Slippery road due to weather (Road Environment Contrib)
Accident 4 of 27

Participant

Vehicle 001
Vehicle 001
Vehicle 001
Vehicle 001
Sunday 18/08/2013 17:00
Weather Fine without high winds
103
403
410
605

Accident Description**Vehicles**

CAR1 TRAV WEST AROUND A3013 COVE ROAD ROUNDABOUT LOST CONTROL ON DAMP ROAD SURFACE CAUSING RIDER TO FALL FROM VEHICLE

1 M/cycle 50 - 125cc Turning right Skid Negative N to W Male Age 42

Casualties

1 Driver or Rider Slight Vehicle no.1 Male 42

Contributory Factors Report 21-June-2018 3

Ancell Farm to Valmead Sch

Accident Date BETWEEN '01-Apr-2013' AND '31-Mar-2018'

Yes

Contributory Factors Confidence

Daylight Daylight

Surface Dry

Grid Coords 482068/155482

Accident Reference:130318602 Slight A3013 COVE RD RBT ANCELLS RD EXIT FLEET

Did a police**officer attend?**

Loss of control (Driver/Rider - Error) Very likely

Accident 5 of 27

Participant

Vehicle 001

Friday 23/08/2013 13:48

Weather Fine without high winds

410

Accident Description**Vehicles**

CAR1 TRAV NORTH ALONG ANCELLS ROAD HAVING TURNED LEFT ROUNDABOUT WHEN DRIVER MISJUDGED THE SPEED LOST CONTROL LEFT ROAD TO NEAR SIDE HITTING LAMPPOST

1 Car Going ahead other No skid Not requested SW to NE Female Age 27

Casualties

1 Driver or Rider Slight Vehicle no.1 Female 27

No - reported

'over the

counter'

Contributory Factors Confidence

Daylight Daylight

Surface Dry

Grid Coords 482143/153871

Accident Reference:130437247 Slight B3010 KINGS RD JW GUILDFORD RD FLEET

Did a police**officer attend?**

Possible

Very likely

Careless/Reckless (Driver/Rider - Behaviour)

Poor turn or manoeuvre (Driver/Rider - Error)

Accident 6 of 27

Participant

Vehicle 002

Vehicle 002

Tuesday 19/11/2013 10:20

Weather Fine without high winds

403

602

Accident Description**Vehicles**

CAR2 TRAV SE B3010 KINGS RD PASSED GUILDFORD RD PERFORMED U TURN COLLIDING WITH M/C1 TRAV NW B3010 KINGS RD CAR2 FAILED TO STOP

1 M/cycle > 500cc Going ahead other No skid Not contacted SE to NW Male Age 53

2 Car U Turn No skid Not traced Age

-1

Not contacted NW to NW

Casualties

1 Driver or Rider Slight Vehicle no.1 Male 53

Contributory Factors Report 21-June-2018 4

Ancell Farm to Valmead Sch

Accident Date BETWEEN '01-Apr-2013' AND '31-Mar-2018'

Yes

Contributory Factors Confidence

Daylight Dark/lights lit

Surface Dry

Grid Coords 482046/155452

Accident Reference:130440053 Slight A3013 ANCELLS RD RBT B3013 COVE RD APPROACH FLEET

Did a police**officer attend?**

Very likely

Very likely

Very likely

Very likely

Inexperienced or learner driver/rider (Driver/Rider - Behaviour)

Careless/Reckless (Driver/Rider - Behaviour)

Loss of control (Driver/Rider - Error)
Exceeding speed limit (Driver/Rider - Injudicious)
Accident 7 of 27

Participant

Vehicle 001
Vehicle 001
Vehicle 001
Vehicle 001
Thursday 21/11/2013 22:58
Weather Fine without high winds
306
410
602
605

Accident Description

Vehicles

CAR1 TRAV NE A3013 COVE RD APPROACHING RBT LOSES CONTROL ON /HAND BEND SPINS INTO CAR2 TRAV SW HAVING LEFT RBT

1 Car Going ahead left hand bend Skid Negative W to NE Male Age 17
2 Car Going ahead other No skid Negative NE to SW Male Age 65

Casualties

1 Driver or Rider Slight Vehicle no.2 Male 65
Yes

Contributory Factors Confidence

Daylight Daylight
Surface Dry
Grid Coords 481390/154989

Accident Reference:140014169 Slight A3013 FLEET RD JW CRANBROOK COURT FLEET

Did a police officer attend?

Other (Special Codes) Very likely
Accident 8 of 27

Participant

Vehicle 001
Monday 13/01/2014 13:02
Weather Fine without high winds
999

Accident Description

Vehicles

CAR1 TRAV NE A3013 FLEET RD WHEN DRIVER SNEEZED TRAFFIC AHEAD HAD SLOWED FOR TRAFFIC LIGHTS AHEAD CAR1 COLLIDED WITH REAR OF CAR2 PUSHING IT INTO THE REAR OF CAR3

1 Car Going ahead other No skid Negative SW to NE Female Age 48
2 Car Waiting to go ahead but held up No skid Negative SW to NE Female Age 18
3 Car Waiting to go ahead but held up No skid Negative SW to NE Male Age 23

Casualties

1 Driver or Rider Slight Vehicle no.1 Female 48
2 Passenger Slight Vehicle no.2 Female 37
3 Passenger Slight Vehicle no.3 Female 18

Contributory Factors Report 21-June-2018 5

Ancell Farm to Valmead Sch

Accident Date BETWEEN '01-Apr-2013' AND '31-Mar-2018'

Yes

Contributory Factors Confidence

Daylight Daylight
Surface Dry
Grid Coords 482180/155418

Accident Reference:140026739 Slight A3013 COVE RD O/S NUMBER 58A FLEET

Did a police officer attend?

Failed to look properly (Driver/Rider - Error) Very likely
Accident 9 of 27

Participant

Vehicle 001
Thursday 23/01/2014 13:34
Weather Fine without high winds
405

Accident Description

Vehicles

CAR1 TRAV EAST A3013 COVE RD FAILS TO SEE AND COLLIDES WITH REAR OF CAR2 STATIONARY WAITING TO TURN RIGHT INTO A RESIDENTIAL ADDRESS

1 Car Going ahead other No skid Negative W to E Female Age 17
2 Car Waiting to turn right No skid Negative W to S Male Age 56

Casualties

1 Driver or Rider Slight Vehicle no.1 Female 17
2 Passenger Slight Vehicle no.1 Female 21
3 Driver or Rider Slight Vehicle no.2 Male 56

Yes

Contributory Factors Confidence

Daylight Daylight
Surface Dry
Grid Coords 482233/155410

Accident Reference:140227070 Serious A3013 COVE RD O/S NUMBER 64 FLEET

Did a police officer attend?

Possible
Possible
Possible
Possible

Failed to look properly (Driver/Rider - Error)
Travelling too fast for conditions (Driver/Rider - Injudicious)
Exceeding speed limit (Driver/Rider - Injudicious)
Defective brakes (Vehicle Defects)
Accident 10 of 27
Distraction in vehicle (Driver/Rider - Impairment)
Distraction outside vehicle (Driver/Rider - Impairment)
Possible
Possible

Participant

Vehicle 002
Vehicle 002
Vehicle 002
Vehicle 002
Vehicle 002
Vehicle 002

Friday 27/06/2014 07:15

Weather Fine without high winds

203
306
307
405
509
510

Accident Description

Vehicles

CAR2 TRAV WEST A3013 COVE RD DRIVER STATES BRAKES FAILED AND VEH COLLIDED WITH REAR OF VAN1 PARKED PARTIALLY ON SOUTH KERB OF A3013 COVE ROAD WITH HAZARD LIGHTS ON

1 Van/Goods < 3.5t Parked No skid Negative Parked Male Age 67

2 Car Going ahead other No skid Negative E to W Male Age 21

Casualties

1 Driver or Rider Slight Vehicle no.1 Male 67
2 Driver or Rider Serious Vehicle no.2 Male 21

Contributory Factors Report 21-June-2018 6

Ancell Farm to Valmead Sch

Accident Date BETWEEN '01-Apr-2013' AND '31-Mar-2018'

Yes

Contributory Factors Confidence

Daylight Daylight
Surface Dry

Grid Coords 482293/153757

Accident Reference:140296417 Serious A323 ALDERSHOT RD J/W A323 NORRIS HILL RD FLEET

Did a police officer attend?

Loss of control (Driver/Rider - Error) Very likely
Accident 11 of 27

Participant

Vehicle 001

Saturday 16/08/2014 12:30

Weather Fine without high winds

410

Accident Description

Vehicles

M/C TURNING RIGHT TO TRAV SOUTHEAST TOWARDS EELMOOR RIDER LOST CONTROL CAUSING MACHINE TO LEAVE C/WAY ON N/S THEN ENTER VERGE

1 M/cycle > 500cc Turning right No skid Negative W to SE Male Age 39

Casualties

1 Driver or Rider Serious Vehicle no.1 Male 39

Yes

Contributory Factors Confidence

Daylight Daylight
Surface Wet/Damp

Grid Coords 481564/155564

Accident Reference:140362328 Slight A3013/B3013 MINLEY RD RBT JW A3013 W/BOUND APPROACH FLEET

Did a police officer attend?

Very likely

Very likely

Disobeyed give way or stop sign markings (Driver/Rider - Injudicious)
Disobeyed give way or stop sign markings (Driver/Rider - Injudicious)

Accident 12 of 27

Participant

Vehicle 001
Vehicle 002

Tuesday 07/10/2014 10:48

Weather Fine without high winds
302
302

Accident Description

Vehicles

CAR1 TRAV SOUTH B3013 MINLEY RD ENTERED RBT AND AT A3013 COVE RD COLLIDED WITH O/SIDE OF CAR2 WHICH ENTERED RBT TO TURN LEFT FROM COVE ROAD.

1 Car Going ahead other No skid Negative N to S Female Age 41
2 Car Turning left No skid Negative E to S Male Age 53

Casualties

1 Driver or Rider Slight Vehicle no.2 Male 53
2 Passenger Slight Vehicle no.2 Female 19

Contributory Factors Report 21-June-2018 7

Ancell Farm to Valmead Sch

Accident Date BETWEEN '01-Apr-2013' AND '31-Mar-2018'

Yes

Contributory Factors Confidence

Daylight Dark/lights lit

Surface Wet/Damp

Grid Coords 481493/155159

Accident Reference:140434102 Serious A3013 STATION RBT JW A3013 FLEET RD NE/BOUND APPROACH FLEET

Did a police

officer attend?

Very likely

Very likely

Failed to look properly (Driver/Rider - Error)

Disobeyed give way or stop sign markings (Driver/Rider - Injudicious)

Accident 13 of 27

Participant

Vehicle 001

Vehicle 001

Thursday 04/12/2014 21:20

Weather Raining without high winds

302

405

Accident Description

Vehicles

CAR1 TRAV NE A3013 FLEET RD ENTERS RBT ACROSS PATH OF P/C2 TRAV NW NEG RBT AND COLLIDES CAUSING RIDER TO FALL OFF

1 Car Going ahead other No skid Negative SW to NE Female Age 66
2 Pedal Cycle Going ahead other No skid Not applicable SE to NW Male Age 44

Casualties

1 Driver or Rider Serious Vehicle no.2 Male 44

No - reported

'over the

counter'

Contributory Factors Confidence

Daylight Daylight

Surface Dry

Grid Coords 481565/155576

Accident Reference:150004763 Slight A3013/B3013 MINLEY RD RBT JW A3013 COVE RD EXIT FLEET

Did a police

officer attend?

Animal or object in carriageway (Road Environment Contrib) Possible

Accident 14 of 27

Participant

Vehicle 001

Monday 05/01/2015 14:19

Weather Fine without high winds

109

Accident Description

Vehicles

M/C1 TRAV SOUTH B3013 MINLEY RD ENTERED RBT INTENDING TO GO STRAIGHT ON BUT HIT BAG OF CABLE TIES LEFT IN ROAD CAUSING RIDER TO FALL

1 M/cycle 50 - 125cc Going ahead other Skid Not contacted N to S Male Age 70

Casualties

1 Driver or Rider Slight Vehicle no.1 Male 70

Contributory Factors Report 21-June-2018 8

Ancell Farm to Valmead Sch

Accident Date BETWEEN '01-Apr-2013' AND '31-Mar-2018'

Yes

Contributory Factors Confidence

Daylight Daylight

Surface Wet/Damp

Grid Coords 481505/154374

Accident Reference:150065546 Serious B3010 KINGS RD JW KENT RD FLEET

Did a police

officer attend?

Failed to look properly (Driver/Rider - Error) Very likely

Accident 15 of 27

Participant

Vehicle 002

Wednesday 25/02/2015 08:00

Weather Raining without high winds

405

Accident Description

Vehicles

P/C2 TRAV SW KENT RD TURNED RIGHT ONTO B3010 KINGS RD COLLIDING WITH CAR1 TRAV SE B3010 KINGS RD

1 Car Going ahead other No skid Negative NW to SE Male Age 50

2 Pedal Cycle Turning right No skid Not applicable NE to NW Male Age 77

Casualties

1 Driver or Rider Serious Vehicle no.2 Male 77

Yes

Contributory Factors Confidence

Daylight Daylight

Surface Dry

Grid Coords 481986/153994

Accident Reference:150104949 Serious B3010 KINGS RD JW NUMBER 119 FLEET

Did a police

officer attend?

Failed to judge other person's path/speed (Driver/Rider - Error) Very likely

Accident 16 of 27

Participant

Vehicle 003

Saturday 28/03/2015 14:25

Weather Fine without high winds

406

Accident Description

Vehicles

CAR1 TRAV SE B3010 KINGS RD SLOWED TO ALLOW CAR2 TO TURN RIGHT INTO KINGS RD FROM A DRIVEWAY OF 119 CAR3 TRAV SE OVERTOOK CAR1 AND COLLIDED WITH O/SIDE OF CAR1

1 Car Stopping No skid Negative NW to SE Female Age 41

2 Car Turning right No skid Negative NE to NW Male Age 69

3 Car O/T moving vehicle on its O/S No skid Negative NW to SE Male Age 21

Casualties

1 Passenger Serious Vehicle no.2 Male 68

2 Driver or Rider Slight Vehicle no.2 Male 69

Contributory Factors Report 21-June-2018 9

Ancell Farm to Valmead Sch

Accident Date BETWEEN '01-Apr-2013' AND '31-Mar-2018'

Yes

Contributory Factors Confidence

Daylight Dark/no lights

Surface Dry

Grid Coords 481540/155368

Accident Reference:150104513 Slight A3013 MINLEY RD O/S NO. 10 FLEET

Did a police

officer attend?

Very likely

Very likely

Very likely

Very likely

Rider wearing dark clothing (Driver/Rider - Impairment)

Impaired by alcohol (Driver/Rider - Impairment)

Careless/Reckless (Driver/Rider - Behaviour)

Impaired by drugs (Driver/Rider - Impairment)

Accident 17 of 27

Illegal turn or direction of travel (Driver/Rider - Injudicious) Very likely

Participant

Vehicle 002

Vehicle 002

Vehicle 002

Vehicle 002

Vehicle 002

Saturday 28/03/2015 02:15

Weather Fine without high winds

502

602

501

507

305

Accident Description

Vehicles

CAR1 TRAV SOUTH TOWARDS FLEET COLLIDED HEAD ON WITH UNLIT P/C2 TRAV NORTH TOWARDS COVE ON WRONG SIDE OF C/WAY

1 Car Going ahead other No skid Negative N to S Female Age 25

2 Pedal Cycle Going ahead other No skid Not applicable S to N Male Age 19

Casualties

1 Driver or Rider Slight Vehicle no.2 Male 19

No - reported

'over the
counter'

Contributory Factors Confidence

Daylight Daylight

Surface Dry

Grid Coords 481552/155573

Accident Reference:150287687 Slight A3013/B3013 MINLEY RD RBT JW A3013 MINLEY RD N/BOUND

APPROACH FLEET

Did a police

officer attend?

Possible

Very likely

Poor turn or manoeuvre (Driver/Rider - Error)

Careless/Reckless (Driver/Rider - Behaviour)

Accident 18 of 27

Participant

Vehicle 001

Vehicle 002

Tuesday 18/08/2015 19:45

Weather Fine without high winds

602

403

Accident Description

Vehicles

CAR1 TRAV NORTH A3013 MINLEY RD IN LANE 1 ENTERED RBT INTENDING TO GO STRAIGHT ON TO B3013 MINLEY RD AND COLLIDED WITH N/SIDE OF CAR2 NEG RBT FROM RIGHT TURN LANE2 TURNING RIGHT FOR COVE ROAD. CAR1 LOST CONTROL

1 Car Going ahead other Skid Not contacted S to N Male Age 25

2 Car Going ahead other No skid Not contacted S to N Male Age 21

Casualties

1 Driver or Rider Slight Vehicle no.1 Male 25

Contributory Factors Report 21-June-2018 10

Ancell Farm to Valmead Sch

Accident Date BETWEEN '01-Apr-2013' AND '31-Mar-2018'

No - reported

'over the
counter'

Contributory Factors Confidence

Daylight Daylight

Surface Dry

Grid Coords 481930/153550

Accident Reference:150413794 Slight VELMEAD RD JW VELMEAD JUNIOR SCHOOL FLEET

Did a police

officer attend?

Failed to look properly (Driver/Rider - Error) Very likely

Accident 19 of 27

Participant

Vehicle 001

Friday 27/11/2015 14:14

Weather Fine without high winds

405

Accident Description

Vehicles

CAR1 TRAV NE ALONG VELMEAD ROAD TURNED RIGHT INTO VELMEAD JUNIOR SCHOOL ACROSS THE PATH OF AND COLLIDED WITH PC2 TRAV SW ALONG VELMEAD ROAD RIDER OF PC2 FELL FROM VEHICLE

1 Car Turning right No skid Not contacted SW to SE Female Age -1

2 Pedal Cycle Going ahead other No skid Not applicable NE to SW Female Age 53

Casualties

1 Driver or Rider Slight Vehicle no.2 Female 53

Yes

Contributory Factors Confidence

Daylight Dark/lights lit

Surface Wet/Damp

Grid Coords 482057/155467

Accident Reference:150448033 Slight A3013 COVE RD JW ANCELLS RD FLEET

Did a police

officer attend?

Possible

Very likely

Failed to look properly (Driver/Rider - Error)

Slippery road due to weather (Road Environment Contrib)

Accident 20 of 27

Participant

Vehicle 001

Vehicle 001

Monday 21/12/2015 18:50

Weather Raining with high winds

103

405

Accident Description

Vehicles

CAR2 TRAV NE ALONG A3013 COVE ROAD STOPPED AT THE RBT AT ANCELLS ROAD CAR1 BEHIND FAILED TO

STOP IN TIME AND COLLIDED WITH THE REAR OF CAR2
1 Car Going ahead other No skid Negative SW to NE Female Age 21
2 Car Waiting to go ahead but held up No skid Not requested SW to NE Female Age 56

Casualties

1 Passenger Slight Vehicle no.2 Female 76
Contributory Factors Report 21-June-2018 11
Ancell Farm to Valmead Sch

Accident Date BETWEEN '01-Apr-2013' AND '31-Mar-2018'
Yes

Contributory Factors Confidence

Daylight Dark/lights lit
Surface Dry
Grid Coords 481311/154862
Accident Reference:160000524 Serious A3013 FLEET RD JW AVONDALE RD FLEET

Did a police officer attend?

Very likely
Very likely
Very likely
Very likely
Failed to judge other person's path/speed (Driver/Rider - Error)
Emergency vehicle on call (Special Codes)
Careless/Reckless (Driver/Rider - Behaviour)
Travelling too fast for conditions (Driver/Rider - Injudicious)
Accident 21 of 27

Participant

Vehicle 001
Vehicle 001
Vehicle 001
Vehicle 001
Friday 01/01/2016 02:23
Weather Fine without high winds
307
602
903
406

Accident Description

Vehicles

POLICE CAR1 TRAV NE ALONG A3013 FLEET ROAD ON EMERGENCY CALL OVERTOOK TAXI3 AND CAR2 AT THE SAME TIME CAR2 TURNED RIGHT INTO AVONDALE ROAD COLLISION OCCURED BETWEEN POLICE CAR1 AND CAR2
1 Car O/T moving vehicle on its O/S No skid Negative SW to NE Male Age 31
2 Car Turning right No skid Negative SW to SE Female Age 51
3 Taxi Going ahead other No skid Not requested SW to NE Male Age 23

Casualties

1 Driver or Rider Slight Vehicle no.1 Male 31
2 Passenger Slight Vehicle no.1 Female 29
3 Driver or Rider Serious Vehicle no.2 Female 51
No - reported
'over the counter'

Contributory Factors Confidence

Daylight Daylight
Surface Dry
Grid Coords 481360/154827
Accident Reference:160290282 Slight AVONDALE ROAD OUTSIDE OF NUMBER 3, FLEET, HAMPSHIRE

Did a police officer attend?

Aggressive driving (Driver/Rider - Behaviour) Very likely
Accident 22 of 27

Participant

Vehicle 001
Wednesday 03/08/2016 19:59
Weather Fine without high winds
601

Accident Description

Vehicles

CAS 1 (PASSENGER) LEANING INTO OPEN WINDOW TALKING TO THE DRIVER OF VEH 1 (CAR) STATIONARY ALONG AVONDALE ROAD, A DISPUTE OCCURS AND VEH 1 MOVES OFF IN A SE DIRECTION WITH CAS 1 STILL IN THE VEH CAUSING THEM TO FALL OVER
1 Car Starting No skid Not traced Age

-1
Not contacted NW to SE

Casualties

1 Passenger Slight Vehicle no.1 Female 27
Contributory Factors Report 21-June-2018 12
Ancell Farm to Valmead Sch
Accident Date BETWEEN '01-Apr-2013' AND '31-Mar-2018'
No - reported
'over the counter'

Contributory Factors Confidence

Daylight Daylight
Surface Dry
Grid Coords 481580/155565
Accident Reference:160354394 Slight A3013 COVE RD/B3013 MINLEY RD RBT FLEET

Did a police officer attend?

Aggressive driving (Driver/Rider - Behaviour) Very likely
Accident 23 of 27

Participant

Vehicle 001
Monday 19/09/2016 17:38
Weather Fine without high winds
601

Accident Description

Vehicles

P/C2 TRAV WEST FROM COVE TOWARDS FLEET PASSING SLOW MOVING TRAFFIC ON N/S MOVED TO O/S TO PASS CAR1 WHICH MOVED TO N/S IN ORDER TO BLOCK P/C2 ON N/S AFTER P/C2 HAD PASSED CAR1 ON O/S DRIVER OF CAR1 COLLIDED WITH REAR O/S OF P/C2

1 Car Going ahead other No skid Not contacted E to W Male Age 33
2 Pedal Cycle Going ahead other No skid Not applicable E to W Male Age 48

Casualties

1 Driver or Rider Slight Vehicle no.2 Male 48

No - reported

'over the counter'

Contributory Factors Confidence

Daylight Daylight
Surface Dry
Grid Coords 481452/155087

Accident Reference:44170069047 Slight A3013 FLEET RD OUTSIDE NO 22 THE SHELL PETROL STATION FLEET

Did a police officer attend?

Possible
Possible
Possible

Failed to signal/misleading signal (Driver/Rider - Error)
Failed to judge other person's path/speed (Driver/Rider - Error)
Failed to look properly (Driver/Rider - Error)

Accident 24 of 27

Participant

Vehicle 002
Vehicle 001
Vehicle 002
Wednesday 22/02/2017 07:35
Weather Fine without high winds
405
406
404

Accident Description

Vehicles

CAR2 TRAV SW ON A3013 FLEET ROAD TURNED RIGHT INTO SHELL PETROL STATION ACROSS THE PATH OF PC1 TRAV NE PC1 COLLIDED WITH NEAR SIDE OF CAR2

1 Pedal Cycle Going ahead other No skid Not applicable SW to NE Male Age 50
2 Car Turning right No skid Not contacted NE to NW Female Age 21

Casualties

1 Driver or Rider Slight Vehicle no.1 Male 50

Contributory Factors Report 21-June-2018 13

Ancell Farm to Valmead Sch

Accident Date BETWEEN '01-Apr-2013' AND '31-Mar-2018'

Yes

Contributory Factors Confidence

Daylight Dark/lights lit
Surface Dry
Grid Coords 481250/154566

Accident Reference:44170321632 Slight B3010 KINGS ROAD AT JUNCTION WITH ALBERT STREET, FLEET, HAMPSHIRE

Did a police officer attend?

Very likely
Very likely
Poor turn or manoeuvre (Driver/Rider - Error)
Failed to look properly (Driver/Rider - Error)

Accident 25 of 27

Participant

Vehicle 002
Vehicle 002
Saturday 19/08/2017 22:40
Weather Fine without high winds
405
403

Accident Description

Vehicles

VEH 2 (CAR) TRAVELLING SE ALONG KINGS ROAD, TURNS RIGHT INTO ALBERT STREET ACROSS THE PATH OF
VEH 1 (CAR) TRAVELLING IN THE OPPOSITE DIRECTION AND COLLIDES.
1 Car Going ahead other No skid Negative SE to NW Male Age 79
2 Car Turning right No skid Negative NW to SW Male Age 23

Casualties

1 Passenger Slight Vehicle no.2 Male 21
No - reported
'over the
counter'

Contributory Factors Confidence

Daylight Dark/lights lit
Surface Dry
Grid Coords 482265/153757

Accident Reference:44170425676 Slight A323 ALDERSHOT ROAD AT JUNCTION WITH B3010 KINGS
ROAD, FLEET, HAMPSHIRE

**Did a police
officer attend?**

Very likely
Very likely
Very likely
Very likely
Careless/Reckless (Driver/Rider - Behaviour)
Careless/Reckless (Driver/Rider - Behaviour)
Failed to look properly (Driver/Rider - Error)
Failed to look properly (Driver/Rider - Error)
Accident 26 of 27

Participant

Vehicle 002
Vehicle 003
Vehicle 002
Vehicle 003
Wednesday 01/11/2017 18:31
Weather Fine without high winds
405
405
602
602

Accident Description

Vehicles

VEH 1 (CAR) TRAVELLING E ON A323 ALDERSHOT RD STOPPED AT TRAFFIC LIGHTS IS HIT FROM BEHIND BY
VEH2 (CAR), DRIVER OF VEH 2 CLAIMS THEY WERE HIT FROM BEHIND BY VEH3 (CAR).
1 Car Waiting to go ahead but held up No skid Not contacted W to E Female Age 37
2 Car Stopping No skid Not contacted W to E Female Age 21
3 Car Stopping No skid Not traced Age
-1
Not contacted W to E

Casualties

1 Driver or Rider Slight Vehicle no.1 Female 37
Contributory Factors Report 21-June-2018 14
Ancell Farm to Valmead Sch
Accident Date BETWEEN '01-Apr-2013' AND '31-Mar-2018'
Yes

Contributory Factors Confidence

Daylight Dark/lights lit
Surface Dry
Grid Coords 481666/154247

Accident Reference:44180112590 Slight B3010 KINGS ROAD OUTSIDE OF NUMBER 73, FLEET,
HAMPSHIRE

**Did a police
officer attend?**

Illness or disability, mental or physical (Driver/Rider - Impairment) Very likely
Accident 27 of 27

Participant

Vehicle 001
Monday 26/03/2018 18:13
Weather Fine without high winds
505

Accident Description

Vehicles

VEH 1 (CAR) TRAVELLING SE ALONG B3010 KINGS ROAD, IT IS BELIEVED THAT THE DRIVER HAS A MEDICAL
EPISODE AND DRIFTS OVER THE CENTRE LINE ACROSS THE PATH OF VEH 2 (CAR) TRAVELLING IN THE
OPPOSITE DIRECTION AND COLLIDES.
1 Car Going ahead other No skid Negative NW to SE Male Age 19
2 Car Going ahead other No skid Negative SE to NW Female Age 49

Casualties

1 Driver or Rider Slight Vehicle no.1 Male 19
2 Driver or Rider Slight Vehicle no.2 Female 49
3 Passenger Slight Vehicle no.2 Female 12
Contributory Factors Report 21-June-2018 15